



NYCHA Construction Management and Controlled Inspection work at Johnson Housing Development

The development is located on the both sides of Lexington Ave bounded by E 115th Street on the north, third avenue on the E 112th Street on the south and The Park Ave on the west. There are ten (10) fourteen-storied buildings on a 12 acres tract with 1297 apartments.

The scope of work for this project was gut rehabilitation of the interior and exterior of all the building including common area and the inside of the building. AG Consulting Engineering provided engineers for this project that were responsible for routine construction management work including controlled inspection work of concrete cast-in-place, concrete mix design, preparation of concrete test cylinder, concrete field tests including slump, air entrant, temperature of concrete and for masonry mortar and grout testing. We also initiated and signed off all the related TR forms of NYCDOB.

Location:

New York, NY

Owner:

NYCHA

Services Provided:

Construction Management



A.G. CONSULTING ENGINEERING, PC

A.G. Consulting Engineering, PC
131W 33rd Street, 12B
New York, NY 10001
Phone: 212-268-0950
agceng@agceng.com